

USER GUIDE

SW-500/SW-200




STEP 1

Push the pins to the outer position.



STEP 2

Secure the device to the winding side of the torsion spring by inserting pins into the cone. Make sure that all pins are firmly in place.



STEP 3

Tighten the spring to the required number of turns using a drill.



STEP 4

Secure the spring by utilizing a 3/8" square socket to tighten the cone screws. Then, remove the SW-500/SW-200 by pushing the pins to the outer position.



WHAT YOU NEED

- Cordless Drill.
- 3/8" square socket



SAFETY INSTRUCTIONS

- Check the tool for damage before use.
- Do not use tool if it is damaged.
- Keep work area clean and well lit.
- Support the device firmly. Keep children and bystanders away when using the tool.
- Do not overreach. Keep your footing steady and balance throughout the entire work process.



* All rights to this manual are reserved. Specifications are subject to change without notice.



Toll Free (855) 931-3334



DevancoCanada.com