

DWGK11

DW 40 Field Setting

P.O. = pressure closes, NO contact

1. turn air bleed set screw clockwise until closed completely, then open (turn counterclockwise) by 3 marks, (marks on the housing)
2. connect buzzer to fast-on tabs (should not buzz) and turn the contact set screw clockwise until you hear the buzzer, from that point turn the screw counterclockwise by 3 marks (marks on the housing)
(if the buzzer sounds upon connection, you will have to slowly turn the contact set screw counterclockwise until the buzzer stops, from that point turn the screw counterclockwise by 3 marks (marks on the housing))

